

994 Sloped Ceiling Pendant Trac Adapter

(Converts straight hanging pendant kits #L992 or L993 to swivel hanging pendant for sloped ceilings.)

Step 1. Discard 5" canopy and 5" diameter stem mtg. plate (if it is not being used as a splice plate in a "T" bar ceiling) from L992 or L993 pendant kits and substitute with parts in L994 45° pendant trac adapter.

Step 2. Assemble mounting strap to outlet box screws or splice plate in a "T" bar ceiling.

Step 3. Assemble swivel ball with (2) set screws (allen wrench provided) to end of 18" stem.

o 4. Slide ball end through mounting strap slot and mount canopy to mounting strap with (2) screws, as shown.

Step 5. For converting #L992 only. Slide pendant bracket cover over stem as shown.

Step 6. Assemble (2) 1/4-28 hex nuts to stem end with approximately 3/8" between the nuts.

Step 7. Assemble pendant bracket to mini trac with #10-24 nut and screw. If Raceway trac, slide pendant bracket on to trac for assembly, and use screws to position.

Step 8. Raise trac with assembled pendant brackets and slide between the 1/4-28 nut on stem end and into slot on pendant bracket.

Step 9. Tighten nuts to secure.

